


## MagiCAD for AutoCAD 2021 UR-1.1 release notes

### MagiCAD for AutoCAD 2021 UR—1.1 fixed issues

#### Room module left some slabs out of heat loss calculations

[Room]

The Room module incorrectly leaves some slabs out of heat loss calculations in MagiCAD for AutoCAD 2021 UR-1. In the example situation below, the calculation missed the roof marked with a red arrow, but the green one was calculated properly. This issue has been fixed in MagiCAD 2021 UR-1.1.



#### Sprinkler calculation did not work properly with BS 9251:2014 and EN 16925 calculation standards

[Sprinkler calculation]

Sprinkler calculation did not work properly with BS 9251:2014 and EN 16925 calculation standards. When the calculation standards were used, MagiCAD returned an error message about missing pipe material information in the pipe series, even if the pipe material was properly defined. This issue has been fixed in MagiCAD 2021 UR-1.1.

#### Unintentional resetting of circuit and device IDs

[Circuit Designer]

Copying objects in MagiCAD Circuit Designer led to circuit and device IDs being unintentionally reset for all parts. The IDs were only supposed to be reset when copying linked child parts, as in that case new IDs are needed. This issue has been fixed in MagiCAD 2021 UR-1.1.