MagiCAD for Revit

Release notes for version 2020 UR-2.1

26/03/2020

MagiCAD

Content

1   Resolved issues

1.1   Common

No resolved issues in this release.

1.2   Ventilation and Piping

Creating a new size of an existing product failed
The family cration of some products failed when the second size of the same product was installed.
The error occurred also when sizing tried to changed the size of an existing family.
This error is now corrected.

Product belonging to "Other pipe components" group with only one connector had an incorrect installation dialog
Products with one connector had an incorrect installation dialog.

1.3   Electrical

No resolved issues in this release.

1.4   Circuit designer

No resolved issues in this release.

1.5   Room

No resolved issues in this release.

1.6   Schematics

No resolved issues in this release.