



MagiCAD for Revit

Release notes for version 2024 UR-2.1

18/03/2024

Content

1	RESOLVED ISSUES	3
1.1	Piping and Ventilation.....	3
1.2	Supports & Hangers.....	3

1 Resolved issues

1.1 Piping and Ventilation

Reducers are getting incorrect OffsetWidth and OffsetHeight after sizing piping network

Issue where some specific pipe reducers got incorrect OffsetHeight and OffsetWidth parameter values when sizing was used. This caused reducer geometry to be incorrect.

1.2 Supports & Hangers

Updating older project with S&H causes Revit to crash

Issue where Revit crashed after user chose "OK" in the following warning dialog: "The version of S&H Model in this project is lower than current version. Please upgrade and save it to keep compatibility."