



MagiCAD for AutoCAD

Release notes for version 2021 UR-1.2

10/12/2020

Content

1	RESOLVED ISSUES	3
1.1	Circuit designer	3

1 Resolved issues

1.1 Circuit designer

Installing busbars caused fatal error

Installing busbar systems led to a fatal error. This problem came as a side-effect from the improvements made to Change Properties.

The issue is now fixed in 2021 UR-1.2. We apologize for the inconvenience.